

Message

From: Keller, Lynn [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=08038B86D66A47D3AACA8BEE1A63A5A7-LKELLER]
Sent: 3/10/2016 6:25:24 PM
To: Fennessy, Christopher [christopher.fennessy@Rocket.com]
Subject: RE: Area 40 Status

That is the plan, Chris, but we need to transition the new contractors to support Area 40 as well—esp given the upcoming FS and waning funds we have available under the CH2MHill ceiling.

Lynn M. Keller, EI, PMP
US EPA Region 9 RPM
75 Hawthorne St, SFD 7-1
San Francisco, CA 94105
415.947.4162

From: Fennessy, Christopher [mailto:christopher.fennessy@Rocket.com]
Sent: Wednesday, March 09, 2016 10:01 AM
To: Keller, Lynn <Keller.Lynn@epa.gov>
Subject: RE: Area 40 Status

I thought CH2M Hill was going to complete reviews of Area 40.

Christopher M. Fennessy, P.E.
Aerojet Rocketdyne, Inc.
Engineering Manager, Site Remediation
11260 Pyrites Way, Suite 125
Rancho Cordova, CA 95670
Ph: 916-355-3341
Fax: 916-355-6145
Email: Christopher.Fennessy@Rocket.com

From: Keller, Lynn [mailto:Keller.Lynn@epa.gov]
Sent: Wednesday, March 09, 2016 9:56 AM
To: Fennessy, Christopher
Subject: [EXTERNAL] RE: Area 40 Status

Hi, Chris. It depends on how long it takes for both EPA and DTSC to agree upon and sign the transfer document. Contractually though we have to be careful on whether we refer to Area 40 as part of OU7 or OU10. We have EA support for review of RI/FS documents for OU7, but not if it's called OU10.

Lynn M. Keller, EI, PMP
US EPA Region 9 RPM
75 Hawthorne St, SFD 7-1
San Francisco, CA 94105
415.947.4162

From: Fennessy, Christopher [mailto:christopher.fennessy@Rocket.com]
Sent: Thursday, March 03, 2016 11:19 AM

To: Keller, Lynn <Keller.Lynn@epa.gov>

Subject: Area 40 Status

Hi Lynn – Based upon your notification that the CERCLA process may require Area 40 to continue through the FS under EPA's oversight, do you anticipate creating OU-10 prior to submittal of the draft FS (Anticipate end of March)?

Thanks, Chris

Christopher M. Fennessy, P.E.

Aerojet Rocketdyne, Inc.

Engineering Manager, Site Remediation

11260 Pyrites Way, Suite 125

Rancho Cordova, CA 95670

Ph: 916-355-3341

Fax: 916-355-6145

Email: Christopher.Fennessy@Rocket.com